

Robert Bosch GmbH
Postfach 10 02 61
31102 Hildesheim
Visitors
Robert-Bosch-Straße 200
31139 Hildesheim
Phone +49 5121 49-0
www.bosch.com

Contact:
Bosch Electronic Service
Phone: +351 253 306 077
Email: service.en@pt.bosch.com

Adjustment of our Service Portfolio for the Independent Aftermarket (IAM) August 06, 2026

Ladies and gentlemen,

We are writing to inform you today about an adjustment to our service portfolio for **independent workshops (IAM)** in the automotive sector. As part of a strategic realignment of the Bosch Electronic Services division, the 1:1 repair service for the Independent Aftermarket (IAM) will be discontinued. This excludes products for workshop equipment.

Key Dates:

- Final order acceptance: August 31, 2026
- Processing of existing 1:1 repair service orders for IAM until October 31, 2026

Background of the Adjustment

Bosch continuously reviews its portfolio and adapts it to changing market requirements and economic conditions. This also includes the targeted discontinuation of services that are no longer part of our strategic focus.

Should you have any questions, your usual contact persons will be happy to assist you.

We thank you for your understanding and past cooperation.
Yours sincerely

p.p. Andreas Wenda

Bosch Electronic Service
Robert Bosch GmbH